#### NOTE:

- 1. The pins are very sharp, keep out of the reach of children!
- 2. To avoid injury, do not point pins at people or animals.
- 3. Keep unit dry and clean to ensure accuracy.
- 4. If not in use for a long period of time, remove the battery.
- 5. Abnormally high readings may be caused by surface salts on newly plastered walls or by contact with metal or steel reinforcing bars etc behind a particular surface.

Spnin Inc. www.sonin.com Made in China

-3-

Thank you for choosing a Sonin Digital Moisture Meter. Please read this manual before use.

### FEATURES:

- · Easy to Read Large LCD display with Low Battery Symbol
- Range: 5% to 40%
- · Resolution: 1%
- · Power: one 9V Battery
- Dimensions: 5" x 2 ½" x 1 ¼"
- · Weight: 4 oz. with battery
- Operating Temperature:

32°F to 104°F (0°C to 40°C) 0-70% RH

# DIGITAL MOISTURE METER OPERATING MANUAL



Push upward with thumb to remove probe cover.



## FRONT PANEL DESCRIPTIONS

- Probe Cover
- Probes 2
- 3 Data Hold button
- 4. Power button
- 5. LCD display
- Battery Cover



### INSTRUCTIONS FOR USE:

- A. Remove back cover and install one 9V battety, pressing tabs firmly in place.
- B. Remove cover by pressing UP upward with your thumb.
- C. Press P to power on unit and then insert the pins approximately 1/8" into wood, wallboard,or material to be tested. The moisture content will display on LCD. WARNING: DO NOT PLUG THE PROBES

INTO ANY ELECTRICAL RECEPTACLES.

- D. To HOLD current reading, press H button. Press H again
- to cancel or to take next reading.
- E. When finished, turn it off by pressing the P button and replace cover on probes.
- F. If a probe is damaged, it can be replaced. The old probe can be taken out by loosening the 5mm nut in a counter-clockwise direction. Remove the old probe and replace with the new probe, then tighten the nut again.